REQUEST FOR QUOTATIONS (RFQ)							PAGE (DF I	PAGES 8			
1. RFQ NO.	IIS IS NOT AN OR	DER) 2. DATE ISSUED		3. REQUI	SITION	NO.		4. TYPE OF	MARKET			
RQ361717		August 21, 2007		RQ361717			side (for	· Washington., [authoriz	ed re-sellers)	
5A. ISSUED BY	:					6. DELIVE			t Aside			
Office of Co Information 441 4 th Stre	nt of the District of the Dist	oup)			RECEIP	NO LATER THAN 10 CALENDAR DAYS AFTER RECEIPT OF PURCHASE ORDER 7. DELIVERY					
wasningtoi	1, DC 20001							_				
5B. FOR INFOR	MATION CALL: (/	Name and telephone no.	.) (No collect ca	lls)		■ FOB DI	ESTINAT	ION 🗆 OTH	IER (See	Schedul	e)	
•	·	list , phone (202) 727	•	02) 727-167	9							
8A. TO: NAME A	AND ADDRESS, IN	NCLUDING ZIP CODE,	OF QUOTER					Consignee and ad		-	IP code)	
		SINESS ENTERPRIS	` '			441 4 th Suite 10	Street, 045N		Office	er		
8B. TAX ID NO. OF QUOTER:				Washin Attentio		DC 20001 ter Olle						
10. PLEASE FU BEFORE:	RNISH QUOTATIO	ONS ON OR	11A. PLEASE	STATE YOU	R SBE (LERTIFICATION NUM	IBER BEI	LOW				
August 31, 20	07, 2:00 PM. (Ea	astern Time)				COLUMBIA SUPPLY	Y SCHEE	DULE (DCSS) CO	NTRACT	FOR TH	ESE ITEMS,	
						TERMS AND CO			F 40	4-	140 D	
hand-delive	r bids to: OCl ubmitting a q	Please complete I P Bid Mail Room, uotation for this	441-4 th Str	eet, NW, S	uite 7	03S, Washingto	n, DC	20001. This i	s the <u>c</u>	<u>nly</u> au	thorized	
the District's F electronic PO District will ap determining th quotation for e	Terms and Conditions: This is a Request For Quotations (RFQ). Quotations submitted are Offers that the District can accept by issuing a Purchase Order (PO), which will incorporate all the terms and conditions of this RFQ. Due to occasional technical issues with the District's PO system, Quoter agrees, by submitting a Quote, to accept a manual PO signed by a Contracting Officer if there is a delay in issuing an electronic PO to invoice against. This RFQ is set-aside for District Small Business Enterprises (SBEs) that are Dell-authorized resellers to the District. The District will apply all percentage preferences, as certified by the Local and Small Business Opportunity Commission, applicable to each Quoter in determining the lowest evaluated quotation for purposes of award. The District will award to the Quoter that submits the lowest evaluated responsive quotation for each line item in this RFQ. If you are unable to submit a quote, please so indicate on this form and return it. This RFQ does not commit the											
requested in b items being re-	lock 13 of this R quested in block	ed in the preparation FQ are of domestic to 13 of this RFQ; and	origin unless o I (3) <u>Quoter ca</u>	otherwise inc an meet the	dicated deadlin	by Quoter; (2) Quo e specified in Block	ter is a l	Dell-authorized s RFQ. The Sta	reseller ndard (to the D	District for the st Provisions	
		mbia Government Sultant PO. For a cop									ınd made a	
part of this Ki	ry and the rest					and local taxes and a			acnine	nts.		
ITEM NO.		SUPPLIES/SI	`			QUANTITY	UNIT	UNIT PRI	CE		AMOUNT	
(A)		(B)				(C)	(D)	(E)			(F1)	
0001		50, Dual Core Xeon Hz FSB (222-3390); 1				3	EA	\$		\$		
	Specifications a	are as follows:										
						-	TOTAL AMOUN	IT (F2)	\$			
14. NAME, ADDRESS, FAX NUMBER AND E-MAIL ADDRESS OF QUOTER					5. SIGNATURE OF PERSON AUTHORIZED TO 16. DATE OF QUOTATION SIGN QUOTATION				QUOTATION			
					17. NA	NAME AND TITLE OF SIGNER (Type or print) 18. TELEPHONE NO. (Include area code)				-		

RFQ NO. RQ361717 2 of 8

Specifications for PowerEdge 2950, Dual Core Xeon Processor 5160, 3.00GHz 4MB Cache, 1333MHz FSB (222-3390):

Dual Core Xeon 2nd Processor 5160, 4MB Cache, 3.00GHz 1333MHz FSB, PE 2950 (311-6222)

16GB 667MHz (4x4GB), Dual Ranked DIMMs (311-6326)

No Keyboard Selected (310-5017)

Broadcom TCP/IP Offload EngineNot Enabled (430-1765)

Riser with 3 PCIe Slots for PowerEdge 2950 (320-4607)

Four 146GB 15K RPM Serial-Attach SCSI 3Gbps 3.5-in HotPlug Hard Drives (341-3922)

PERC 5/i, x6 Backplane Integrated Controller Card (341-3066)

No Floppy Drive for x6 Backplane (341-3685)

Windows Server 2003 R2 Standard x64 Edition with SP2 Includes 5 CALs (420-7122)

Mouse Option None (310-0024)

Embedded Broadcom NetXtreme II5708 GigabitEthernet NIC (430-1764)

Dell Remote Access Card, 5th Generation for PowerEdge Remote Management (313-3923)

24X IDE CD-RW/DVD ROM Drive for PowerEdge 2950 (313-3934)

Bezel for PE 2950 (313-3920)

1x6 Backplane for 3.5-inch Hard Drives (311-5747)

Electronic Documentation and OpenManage CD Kit, PE2950 (310-7415)

146GB 15K RPM Serial-Attach SCSI 3Gbps 3.5-in HotPlug HardDrive (341-3031)

Integrated SAS/SATA RAID 5 PERC 5/i Integrated (341-3060)

Rack Chassis w/Sliding Rapid/Versa Rails and Cable Management Arm, Universal (310-7412)

Premier Enterprise SupportService Gold Welcome Letter (310-3785)

GOLD Enterprise Support: 4 Hour 7x24 Onsite Service with Emergency Dispatch,2 YR Ext (960-8322)

GOLD Enterprise Support: 7x24 Escalation Manager, Hw/Sw Tech Phone Support, Enterprise Command Center, 3Yr (960-8572)

GOLD Enterprise Support: 4 Hour 7x24 Onsite Service with Emergency Dispatch, Init YR (970-4190)

Dell Hardware Warranty Plus Onsite Service Inital YR (984-1399)

Dell Hardware Warranty, Extended YR (984-1417)

RFQ NO. RQ361717 3 of 8

On-Site Installation Declined (900-9997)

Redundant Power Supply with Dual Cords for PowerEdge 2950 (310-7422)

Microsoft SQL Server 2005X64 Standard (2 Socket), OEM, NFI (420-5697)

ITEM NO.	SUPPLIES/SERVICES	QUANTITY	UNIT	UNIT PRICE	AMOUNT
(A)	(B)	(C)	(D)	(E)	(F1)
0002	BIG-IP Local Traffic Manager v9 - 3400 Series (A0396399)	2	EA	\$	\$
	Total No. of System Groups: 0				
0003	146GB 15K RPM Serial-Attach SCSI 3 Gbps 3.5-in HotPlug HardDrive, Cust. Kit (341-2827)	2	EA	\$	\$
0004	146G,10K,SAS3G,2.5,HP,CU (341-4733)	2	EA	\$	\$
0005	500GB 7.2K RPM Universal SATA 3Gbps 3.5-in HotPlug Hard Drive, Cust. Kit (341-3932)	2	EA	\$	\$
0006	Dell EMC AX150 SP (Single Processor) Array DELL-R (222-3105); Total No. of System Groups: 0	2	EA	\$	\$
	Specifications are as follows:				

Hard Drive:	Four 500GB 7.2K RPM Serial ATA3Gbps 3.5-in HotPlug Hard Drives (341-3157)
Hard Drive Controller:	QLOGIC QLE220 FC4 Single Channel Four HBAs (341-4173)
Sound Card:	Power Cord Kit, AX, US, DELL (310-7605)
Cable:	10M MULTI-MODE FC CABLE LC-LC Tyco (310-5626)
Additional Storage Products:	500GB 7.2K RPM Serial ATA 3Gbps 3.5-in HotPlug Hard Drive (341-3163)
Controller Option:	Switch, 4 Gbit, FC4, 200E Brocade (310-7063)
Feature	Versa Rail, AX DELL (310-7604)
Feature	Rapid Rails for 8/16 Port FC-2 Brocade Switches to be installed in a Dell Rack (310-1949)
Service:	4HR/7X24 NO L2, EMC, Unisys, INIT, (AX150) (950-9550)
Service:	Thank You for buying Dell (983-2207)
Service:	4HR/7X24 NO L2, EMC, Unisys, 2year extended (AX150) (950-1282)
Service:	Please visit WWW.Dell.COM (983-2217)
Service:	Premium Enterprise Support - Gold - Premium Services (950-1382)
Service:	Advanced Software Enchancementand Upgrade 3 Years (950-1312)
Installation:	Dell Phone Assisted Installation, AX150 Setup (to schedule, please call 800-945-DELL or 800-945-3355) (983-7207)
Misc:	350W Additional Power Supply for SP Only (310-7651)
Misc:	Three 500GB 7.2K RPM Serial ATA 3Gbps 3.5-in HotPlug Hard Drives (341-3160)
Misc:	Four 500GB 7.2K RPM Serial ATA3Gbps 3.5-in HotPlug Hard Drives (341-3157)
Misc:	10M MULTI-MODE FC CABLE LC-LC Tyco (310-5626)
Misc:	10M MULTI-MODE FC CABLE LC-LC Tyco (310-5626)
Misc:	10M MULTI-MODE FC CABLE LC-LC Tyco (310-5626)

RFQ NO. RQ361717 4 of 8

ITEM NO.	SUPPLIES/SERVICES	QUANTITY	UNIT	UNIT PRICE	AMOUNT
(A)	(B)	(C)	(D)	(E)	(F1)
0007	ENCLOSURE, NO BLADES, PE1855, 1.1 Enclosure with no	1	EA	\$	\$
(Group 1)	Blades, 2 Power Supplies for PowerEdge-R (222-2134); Total No. of System Groups: 2; Specifications are as follows:				

No Keyboard Option,for Dell PowerApps,Tied (310-0900)

Mouse Option None (310-0024)

Media Tray option for externalCD or floppy drive on PE1855 (313-3119)

DVD-ROM, 8x, External USB Black (313-4219)

Front Dongle Cable for USB and KVM Connectivity (310-6257)

Documentation, PE1855, English (310-6258)

Rack Chassis w/Rapid Rails forDell, HPQ or other Square HoleRacks, PE1855 (310-5820)

Premier Enterprise SupportService Gold Welcome Letter (310-3785)

Premier Enterprise Support -Complex Resolutions w/AdvancedSoftware Support - 3 Pack -Exp. 3 Years (950-0117)

Type 2 Contract Same Day 4HR Parts and Labor On-Site Response, Two Years (950-6912)

Premier Enterprise Support - Gold - Premium Services, 3YR Extended (950-6962)

Type 2 Contract Same Day 4HR Parts and Labor On-Site Response,Initial Year (960-3630)

Premier Enterprise On Demand Engineer Dispatch Severity 1 Three Years (970-0237)

Thank You for buying Dell (983-2207)

Please visit WWW.Dell.COM (983-2217)

Dell Education Services OnlineEnterprise Training included w/purchase, take courses at LearnDell.com 90-Day Acc (983-7037)

On-Site Installation Declined (900-9997)

Power Supply Units, 2x2100 Watt, Redundant, PowerEdge 1855 Enclosure (310-6491)

Enclosure Blade Blanks (310-6177) - Quantity 8

Windows Server 2003 R2 Standard Edition, Media Kit (420-5807)

2 GB Enet PowerConnect Switch IO Bays 1-2 or 3-4(w/ EthernetDaughtercard) (430-1082)

Keyboard, Video and Mouse Switch, Digital for PowerEdge 1855 Enclosure (430-1432)

24Amp, 208 Volt, High-Power Power Distribution Unit (PDU) (310-1878)

RFQ NO. RQ361717 5 of 8

0007 (Group 2)	Quad Core L5310 Processor 2x4MB Cache, 1.6GHz, Xeon 1066MHz Front Side Bus for PowerEdge 1955 (222-8500)	2	EA	\$ \$
	Specifications are as follows:			

Quad Core L5310 2nd Processor 2x4MB Cache, 1.6GHz, Xeon 1066MHz FSB for PowerEdge 1955 (311-7169)

4GB 667MHz (4X1GB), Dual Ranked DIMMs (311-6174)

Broadcom Dual Port TCP/IP Offload Engine Not Enabled (430-1763)

146G,10K,SAS3G,2.5,HP (341-4732)

Windows Server 2003 R2 Standard Edition with SP2 Includes 5 CALs (420-7126)

146G,10K,SAS3G,2.5,HP (341-4732)

SAS-SATA, RAID 1, 2 Hard Drives attached to onboard SAS-SATA Controller (341-3338)

Premier Enterprise SupportService Gold Welcome Letter (310-3785)

GOLD Enterprise Support: 4 Hrs 7x24 On Site Service with Emergency Dispatch,2 YR Ext (960-6782)

GOLD Enterprise Support: 7x24 Escalation Manager, Hw/Sw Tech Phone Support, Enterprise Command Center, 3Yr (960-7042)

GOLD Enterprise Support: 4 Hrs7x24 On Site Service with Emergency Dispatch,Init YR (970-2990)

Dell Hardware Warranty Plus OnSite Service Inital YR (984-1578)

Dell Hardware Warranty, Extended YR (984-1587)

On-Site Installation Declined (900-9997)

0008	ENCLOSURE,NO BLADES,PE1855,1.1Enclosure with no Blades, 2	1	EA	\$ \$
(Group 1)	Power Supplies for PowerEdge-R (222-2134); Total No. of System			
(Group 1)	Groups: 2; Specifications are as follows:			

No Keyboard Option,for Dell PowerApps,Tied (310-0900)

Mouse Option None (310-0024)

Media Tray option for externalCD or floppy drive on PE1855 (313-3119)

DVD-ROM, 8x, External USB Black (313-4219)

Front Dongle Cable for USB andKVM Connectivity (310-6257)

Documentation, PE1855, English (310-6258)

Rack Chassis w/Rapid Rails forDell, HPQ or other Square HoleRacks, PE1855 (310-5820)

Premier Enterprise SupportService Gold Welcome Letter (310-3785)

Premier Enterprise Support -Complex Resolutions w/AdvancedSoftware Support - 3 Pack -Exp. 3 Years (950-0117)

Type 2 Contract Same Day 4HR Parts and Labor On-Site Response, Two Years (950-6912)

Premier Enterprise Support - Gold - Premium Services, 3YR Extended (950-6962)

Type 2 Contract Same Day 4HR Parts and Labor On-Site Response, Initial Year (960-3630)

Premier Enterprise On Demand Engineer Dispatch Severity 1 Three Years (970-0237)

Thank You for buying Dell (983-2207)

Please visit WWW.Dell.COM (983-2217)

Dell Education Services OnlineEnterprise Training included w/purchase, take courses at LearnDell.com 90-Day Acc (983-7037)

On-Site Installation Declined (900-9997)

Power Supply Units, 2x2100 Watt, Redundant, PowerEdge 1855 Enclosure (310-6491)

Enclosure Blade Blanks (310-6177) - Quantity 8

Windows Server 2003 R2 Standard Edition, Media Kit (420-5807)

2 GB Enet PowerConnect Switch IO Bays 1-2 or 3-4(w/ EthernetDaughtercard) (430-1082)

Keyboard, Video and Mouse Switch, Digital for PowerEdge 1855 Enclosure (430-1432)

24Amp, 208 Volt, High-Power Power Distribution Unit (PDU) (310-1878)

0008 (Group 2)	Quad Core L5310 Processor 2x4MB Cache, 1.6GHz, Xeon 1066MHz Front Side Bus for PowerEdge 1955 (222-8500);	2	EA	\$ \$
	Specifications are as follows:			

Quad Core L5310 2nd Processor 2x4MB Cache, 1.6GHz, Xeon 1066MHz FSB for PowerEdge 1955 (311-7169)

4GB 667MHz (4X1GB), Dual Ranked DIMMs (311-6174)

Broadcom Dual Port TCP/IP Offload Engine Not Enabled (430-1763)

146G,10K,SAS3G,2.5,HP (341-4732)

Windows Server 2003 R2 Standard Edition with SP2 Includes 5 CALs (420-7126)

146G,10K,SAS3G,2.5,HP (341-4732)

SAS-SATA, RAID 1, 2 Hard Drives attached to onboard SAS-SATA Controller (341-3338)

Premier Enterprise SupportService Gold Welcome Letter (310-3785)

GOLD Enterprise Support: 4 Hrs 7x24 On Site Service with Emergency Dispatch, 2 YR Ext (960-6782)

GOLD Enterprise Support: 7x24 Escalation Manager, Hw/Sw Tech Phone Support, Enterprise Command Center, 3Yr (960-7042)

GOLD Enterprise Support: 4 Hrs7x24 On Site Service with Emergency Dispatch,Init YR (970-2990)

Dell Hardware Warranty Plus OnSite Service Inital YR (984-1578)

Dell Hardware Warranty, Extended YR (984-1587)

On-Site Installation Declined (900-9997)

0009	ENCLOSURE,NO BLADES,PE1855,1.1Enclosure with no Blades, 2	1	EA	\$ \$
(Group 1)	Power Supplies for PowerEdge-R (222-2134); Total No. of System			
(Group 1)	Groups: 2)			
	Specifications are as follows:			

ENCLOSURE, NO BLADES, PE1855, 1.1 Enclosure with no Blades, 2 Power Supplies for PowerEdge-R (222-2134)

No Keyboard Option,for Dell PowerApps,Tied (310-0900)

Mouse Option None (310-0024)

Media Tray option for externalCD or floppy drive on PE1855 (313-3119)

DVD-ROM, 8x, External USB Black (313-4219)

Front Dongle Cable for USB and KVM Connectivity (310-6257)

Documentation, PE1855, English (310-6258)

Rack Chassis w/Rapid Rails forDell, HPQ or other Square HoleRacks, PE1855 (310-5820)

Premier Enterprise SupportService Gold Welcome Letter (310-3785)

Premier Enterprise Support -Complex Resolutions w/AdvancedSoftware Support - 3 Pack -Exp. 3 Years (950-0117)

Type 2 Contract Same Day 4HR Parts and Labor On-Site Response, Two Years (950-6912)

Premier Enterprise Support - Gold - Premium Services, 3YR Extended (950-6962)

Type 2 Contract Same Day 4HR Parts and Labor On-Site Response, Initial Year (960-3630)

Premier Enterprise On Demand Engineer Dispatch Severity 1 Three Years (970-0237)

Thank You for buying Dell (983-2207)

Please visit WWW.Dell.COM (983-2217)

Dell Education Services OnlineEnterprise Training included w/purchase, take courses at LearnDell.com 90-Day Acc (983-7037)

On-Site Installation Declined (900-9997)

Power Supply Units, 2x2100 Watt, Redundant, PowerEdge 1855 Enclosure (310-6491)

RFQ NO. RQ361717 8 of 8

Enclosure Blade Blanks (310-6177) - Quantity 8

Windows Server 2003 R2 Standard Edition, Media Kit (420-5807)

2 GB Enet PowerConnect Switch IO Bays 1-2 or 3-4(w/ EthernetDaughtercard) (430-1082)

Keyboard, Video and Mouse Switch, Digital for PowerEdge 1855 Enclosure (430-1432)

24Amp, 208 Volt, High-Power Power Distribution Unit (PDU) (310-1878)

0009	Quad Core L5310 Processor 2x4MB Cache, 1.6GHz, Xeon 1066MHz Front Side Bus for PowerEdge 1955 (222-8500)	2	EA	\$ \$
(Group 2)	1000MHZ FIORE Side Bus for Fower Edge 1933 (222-6300)			
	Specifications are as follows:			

Quad Core L5310 2nd Processor 2x4MB Cache, 1.6GHz, Xeon 1066MHz FSB for PowerEdge 1955 (311-7169)

4GB 667MHz (4X1GB), Dual Ranked DIMMs (311-6174)

Broadcom Dual Port TCP/IP Offload Engine Not Enabled (430-1763)

146G,10K,SAS3G,2.5,HP (341-4732)

Windows Server 2003 R2 Standard Edition with SP2 Includes 5 CALs (420-7126)

146G,10K,SAS3G,2.5,HP (341-4732)

SAS-SATA, RAID 1, 2 Hard Drives attached to onboard SAS-SATA Controller (341-3338)

Premier Enterprise SupportService Gold Welcome Letter (310-3785)

GOLD Enterprise Support: 4 Hrs 7x24 On Site Service with Emergency Dispatch,2 YR Ext (960-6782)

GOLD Enterprise Support: 7x24 Escalation Manager, Hw/Sw Tech Phone Support, Enterprise Command Center, 3Yr (960-7042)

GOLD Enterprise Support: 4 Hrs7x24 On Site Service with Emergency Dispatch,Init YR (970-2990)

Dell Hardware Warranty Plus OnSite Service Inital YR (984-1578)

Dell Hardware Warranty, Extended YR (984-1587)

On-Site Installation Declined (900-9997)